

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,092,794 B1  
APPLICATION NO. : 09/679853  
DATED : October 5, 2000  
INVENTOR(S) : Mark Alexander Hill et al.

Page 1 of 1


It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**TITLE: METHOD AND APPARATUS FOR CONNECTING TO HVAC DEVICE**

- i) in Column 6, Line 23. The reference to "said server" is incomplete and should be replaced with --said server; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself;--.
- ii) in Column 6, Line 55. The reference to "entry device" is incomplete and should be replaced with --entry device; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself;--.
- iii) in Column 8, Line 3. The reference to "status information; and" is incomplete and should be replaced with --status information; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself--.

Signed and Sealed this

Fourteenth Day of November, 2006



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*